




APPENDIX A – EXISTING ACCESS MANAGEMENT **FIGURES**













Match with Figure A-5

Match with Figure A-7

Driveway exceeds width standard; insufficient driveway spacing

Corner clearance insufficient; insufficient driveway spacing



